

Silver, Wendy

From:
Sent: Wednesday, September 18, 2013 1:32 PM
To: Clark, Richard; Silver, Wendy
Subject: pictures
Attachments: 2013.09.16 036.jpg; 2013.09.16 037.jpg; 2013.09.16 038.jpg; 2013.09.16 041.jpg; 2013.09.16 042.jpg; 2013.04.06 025.jpg

#36, #37 and #42 sediment coming onto driveway

#38. Mr. Johnson opening the valve. The valve is not set in-line with the culvert. It hits the side of the bank at an angle. There are pieces of concrete down there, but we are concerned about erosion to the bank.

(#41) shows creek full.

#25 our driveway last spring.











